SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

03 January 2023

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.257-AAM1.v1-03/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 03/01/2023
**Sample Analysis Date:** 03/01/2023
**Period of Sampling:** 03/01/2023 06:30 AM - 03/01/2023 01:45 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.257/3119/030123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 1.0/100 | <0.01 |
| S110355.257/S444/030123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.257/S577/030123 | MSCP site, temp fencing in front of site sheds, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.257/6255/030123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.257/S975/030123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.257/S1030/030123 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.257/S338/030123 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.257/S1028/030123 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.257/S756/030123 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |
| S110355.257/S520/030123 | PSB site, eastern corner, temp fencing in site, facing West | 0.5/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

03 January 2023

| | | | |
|---|---|---|---|
| S110355.257/S832/030123 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.257/S103/030123 | Mons Road, entry point | 2.0/100 | <0.01 |
| S110355.257/S583/030123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

03 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

03 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

04 January 2023

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.258-AAM1.v1-04/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 04/01/2023
**Sample Analysis Date:** 04/01/2023
**Period of Sampling:** 04/01/2023 06:40 AM - 04/01/2023 01:44 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.258/S597/040123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.258/S077/040123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.258/S205/040123 | MSCP site, temp fencing in front of site sheds, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.258/S706/040123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.258/S139/040123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.258/S813/040123 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.258/S756/040123 | PSB site, western end, fencing along CASB loading dock | 1.0/100 | <0.01 |
| S110355.258/S1010/040123 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.258/S384/040123 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |
| S110355.258/S231/040123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

04 January 2023

| | | | |
|---|---|---|---|
| S110355.258/S089/040123 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.258/S082/040123 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.258/S1031/040123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

04 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

04 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

05 January 2023

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.259-AAM1.v1-05/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 05/01/2023
**Sample Analysis Date:** 05/01/2023
**Period of Sampling:** 05/01/2023 06:40 AM - 05/01/2023 01:51 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.259/S055/050123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.259/3215/050123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.259/S1038/050123 | MSCP site, temp fencing in front of site sheds, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.259/S934/050123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.259/S797/050123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.259/S898/050123 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.259/S104/050123 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.259/S418/050123 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.259/S1021/050123 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |
| S110355.259/S1017/050123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

05 January 2023

| | | | |
|---|---|---|---|
| S110355.259/S997/050123 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.259/6530/050123 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.259/S515/050123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

05 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

05 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA
WORLD RECOGNISED ACCREDITATION
Accredited for compliance with ISO/IEC 17025 - Testing

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

06 January 2023


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.260-AAM1.v1-06/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 06/01/2023
**Sample Analysis Date:** 06/01/2023
**Period of Sampling:** 06/01/2023 06:40 AM - 06/01/2023 01:44 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.260/S518/060123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.260/S097/060123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.260/S724/060123 | MSCP site, temp fencing in front of site sheds, between clean and dirty zone | Rejected: Damaged filter | |
| S110355.260/S199/060123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.260/S227/060123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.260/S913/060123 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.260/S902/060123 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.260/S971/060123 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.260/S106/060123 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |
| S110355.260/S850/060123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

06 January 2023

| | | | |
|---|---|---|---|
| S110355.260/S087/060123 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.260/S911/060123 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.260/S587/060123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

06 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

06 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

09 January 2023

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.261-AAM1.v1-07/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 07/01/2023
**Sample Analysis Date:** 09/01/2023
**Period of Sampling:** 07/01/2023 06:40 AM - 07/01/2023 02:40 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.261/5410/070123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.261/9092/070123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.261/S500/070123 | MSCP site, temp fencing in front of site sheds, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.261/5793/070123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.261/5406/070123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.261/S196/070123 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.261/S909/070123 | PSB site, western end, fencing along CASB loading dock | 1.0/100 | <0.01 |
| S110355.261/S197/070123 | PSB site, fencing behind site sheds | 1.0/100 | <0.01 |
| S110355.261/S855/070123 | PSB site, northern end, temp fencing between site and compound | 1.0/100 | <0.01 |
| S110355.261/S778/070123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

09 January 2023

| | | | |
|---|---|---|---|
| S110355.261/8656/070123 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.261/S588/070123 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.261/S014/070123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

09 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

09 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

09 January 2023

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.262-AAM1.v1-09/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 09/01/2023
**Sample Analysis Date:** 09/01/2023
**Period of Sampling:** 09/01/2023 07:00 AM - 09/01/2023 01:46 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.262/S1001/090123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.262/S757/090123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.262/6392/090123 | MSCP site, temp fencing in front of site sheds, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.262/S998/090123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.262/S947/090123 | MSCP site, northwest, fencing along Redbank Rd | 1.0/100 | <0.01 |
| S110355.262/3360/090123 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.262/S113/090123 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.262/5703/090123 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.262/6367/090123 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |
| S110355.262/3546/090123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

09 January 2023

| | | | |
|---|---|---|---|
| S110355.262/S535/090123 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.262/S1014/090123 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.262/S469/090123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

09 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

09 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

10 January 2023

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.263-AAM1.v1-10/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 10/01/2023
**Sample Analysis Date:** 10/01/2023
**Period of Sampling:** 10/01/2023 06:40 AM - 10/01/2023 12:40 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.263/S1026/100123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.263/S132/100123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.263/S918/100123 | MSCP site, temp fencing in front of site sheds, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.263/S576/100123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.263/5435/100123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.263/S481/100123 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.263/S058/100123 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.263/S466/100123 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.263/3082/100123 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |
| S110355.263/S732/100123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

10 January 2023

| | | | |
|---|---|---|---|
| S110355.263/3385/100123 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.263/S851/100123 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.263/3447/100123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

10 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

10 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

11 January 2023

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.264-AAM1.v1-11/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 11/01/2023
**Sample Analysis Date:** 11/01/2023
**Period of Sampling:** 11/01/2023 06:40 AM - 11/01/2023 02:09 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.264/S332/110123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 1.0/100 | <0.01 |
| S110355.264/S224/110123 | MSCP site, temp fencing in front of site sheds, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.264/S595/110123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.264/6648/110123 | MSCP site, northwest, fencing along Redbank Rd | 1.0/100 | <0.01 |
| S110355.264/S222/110123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.264/S529/110123 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.264/S183/110123 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.264/3436/110123 | PSB site, fencing behind site sheds | 1.0/100 | <0.01 |
| S110355.264/S1037/110123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |
| S110355.264/3249/110123 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

11 January 2023

| | | | |
|---|---|---|---|
| S110355.264/S1035/110123 | Mons Road, before boom gate, fencing | 1.0/100 | <0.01 |
| S110355.264/S1036/110123 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.264/6255/110123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

11 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

11 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

12 January 2023

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.265-AAM1.v1-12/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 12/01/2023
**Sample Analysis Date:** 12/01/2023
**Period of Sampling:** 12/01/2023 06:40 AM - 12/01/2023 01:37 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.265/S220/120123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.265/S103/120123 | MSCP site, Southeast fence, walkway | 0.0/100 | <0.01 |
| S110355.265/S601/120123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.265/S520/120123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.265/S231/120123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.265/S525/120123 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.265/3119/120123 | PSB site, western end, fencing along CASB loading dock | 1.0/100 | <0.01 |
| S110355.265/S995/120123 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.265/S338/120123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |
| S110355.265/S592/120123 | PSB site, northern end, temp fencing between clean and dirt zone | 0.0/100 | <0.01 |
| S110355.265/S237/120123 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

12 January 2023

| | | | |
|---|---|---|---|
| S110355.265/S795/120123 | Mons Road, entry point | 1.0/100 | <0.01 |
| S110355.265/S123/120123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

12 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

12 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

13 January 2023

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.266-AAM1.v1-13/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 13/01/2023
**Sample Analysis Date:** 13/01/2023
**Period of Sampling:** 13/01/2023 06:40 AM - 13/01/2023 01:38 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.266/S1030/130123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.266/S465/130123 | MSCP site, Southeast fence, walkway | 0.0/100 | <0.01 |
| S110355.266/S975/130123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.266/S230/130123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.266/S928/130123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.266/S715/130123 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.266/S444/130123 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.266/S1008/130123 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.266/S583/130123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |
| S110355.266/S001/130123 | PSB site, northern end, temp fencing between clean and dirt zone | 0.0/100 | <0.01 |
| S110355.266/S494/130123 | Mons Road, before boom gate, fencing | 1.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

13 January 2023

| | | | |
|---|---|---|---|
| S110355.266/S982/130123 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.266/S461/130123 | Field Blank | 0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

13 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

13 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

16 January 2023

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.267-AAM1.v1-14/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 14/01/2023
**Sample Analysis Date:** 16/01/2023
**Period of Sampling:** 14/01/2023 06:40 AM - 14/01/2023 02:40 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.267/S791/140123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.267/S577/140123 | MSCP site, Southeast fence, walkway | 1.0/100 | <0.01 |
| S110355.267/S741/140123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.267/S846/140123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.267/3221/140123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.267/2113/140123 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.267/S1029/140123 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.267/S756/140123 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.267/S215/140123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |
| S110355.267/S780/140123 | PSB site, northern end, temp fencing between clean and dirt zone | 1.0/100 | <0.01 |
| S110355.267/6634/140123 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

16 January 2023

| | | | |
|---|---|---|---|
| S110355.267/S181/140123 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.267/S934/140123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

16 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

16 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

16 January 2023

NATA WORLD RECOGNISED ACCREDITATION

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.268-AAM1.v1-16/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 16/01/2023
**Sample Analysis Date:** 16/01/2023
**Period of Sampling:** 16/01/2023 06:40 AM - 16/01/2023 01:59 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.268/S770/160123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.268/S740/160123 | MSCP site, Southeast fence, walkway | 0.0/100 | <0.01 |
| S110355.268/S119/160123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.268/S1011/160123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.268/S821/160123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.268/S1040/160123 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.268/S926/160123 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.268/S337/160123 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.268/S1033/160123 | PSB site, eastern corner, temp fencing in site, facing West | Rejected: Pump Missing | |
| S110355.268/5489/160123 | PSB site, northern end, temp fencing between clean and dirt zone | 0.0/100 | <0.01 |
| S110355.268/S007/160123 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

16 January 2023

| | | | |
|---|---|---|---|
| S110355.268/S195/160123 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.268/S620/160123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

16 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

16 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

17 January 2023

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.269-AAM1.v1-17/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 17/01/2023
**Sample Analysis Date:** 17/01/2023
**Period of Sampling:** 17/01/2023 06:26 AM - 17/01/2023 01:39 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.269/S009/170123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 1.0/100 | <0.01 |
| S110355.269/S958/170123 | MSCP site, Southeast fence, walkway | 0.0/100 | <0.01 |
| S110355.269/5507/170123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.269/S822/170123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.269/S1015/170123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.269/S979/170123 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.269/S1039/170123 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.269/5503/170123 | PSB site, fencing behind site sheds | Rejected: Pump Missing | |
| S110355.269/S1027/170123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |
| S110355.269/2043/170123 | PSB site, northern end, temp fencing between clean and dirt zone | 0.0/100 | <0.01 |
| S110355.269/S108/170123 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

17 January 2023

| | | | |
|---|---|---|---|
| S110355.269/3193/170123 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.269/S773/170123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

17 January 2023






**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

17 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

18 January 2023

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.270-AAM1.v1-18/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 18/01/2023
**Sample Analysis Date:** 18/01/2023
**Period of Sampling:** 18/01/2023 06:40 AM - 18/01/2023 01:40 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.270/S582/180123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.270/S529/180123 | MSCP site, Southeast fence, walkway | 0.0/100 | <0.01 |
| S110355.270/S123/180123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.270/S229/180123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.270/S338/180123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.270/S1036/180123 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.270/S995/180123 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.270/3249/180123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |
| S110355.270/3119/180123 | PSB site, northern end, temp fencing between clean and dirt zone | 0.0/100 | <0.01 |
| S110355.270/S074/180123 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.270/S252/180123 | Mons Road, entry point | 1.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

18 January 2023

| | | | |
|---|---|---|---|
| S110355.270/S716/180123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

18 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

18 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

19 January 2023

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.271-AAM1.v1-19/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 19/01/2023
**Sample Analysis Date:** 19/01/2023
**Period of Sampling:** 19/01/2023 06:40 AM - 19/01/2023 02:08 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.271/S140/190123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.271/S992/190123 | MSCP site, Southeast fence, walkway | 1.0/100 | <0.01 |
| S110355.271/3065/190123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.271/6255/190123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.271/S97/190123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.271/S222/190123 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.271/6305/190123 | PSB site, western end, fencing along CASB loading dock | 1.0/100 | <0.01 |
| S110355.271/S391/190123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |
| S110355.271/S1032/190123 | PSB site, northern end, temp fencing between clean and dirt zone | 0.0/100 | <0.01 |
| S110355.271/S573/190123 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.271/S237/190123 | Mons Road, entry point | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

19 January 2023

| | | | |
|---|---|---|---|
| S110355.271/S490/190123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

19 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

19 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

20 January 2023

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.272-AAM1.v1-20/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 20/01/2023
**Sample Analysis Date:** 20/01/2023
**Period of Sampling:** 20/01/2023 06:40 AM - 20/01/2023 02:10 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.272/S534/200123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 1.0/100 | <0.01 |
| S110355.272/S280/200123 | MSCP site, Southeast fence, walkway | 0.0/100 | <0.01 |
| S110355.272/S935/200123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.272/2048/200123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.272/S795/200123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.272/S102/200123 | PSB site, northern end, fencing along Redbank Rd | 1.0/100 | <0.01 |
| S110355.272/S103/200123 | PSB site, western end, fencing along CASB loading dock | 1.0/100 | <0.01 |
| S110355.272/S590/200123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |
| S110355.272/3336/200123 | PSB site, northern end, temp fencing between clean and dirt zone | 0.0/100 | <0.01 |
| S110355.272/S053/200123 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.272/3530/200123 | Mons Road, entry point | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

20 January 2023

| | | | |
|---|---|---|---|
| S110355.272/S512/200123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

20 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

20 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

23 January 2023

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.273-AAM1.v1-21/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 21/01/2023
**Sample Analysis Date:** 23/01/2023
**Period of Sampling:** 21/01/2023 06:40 AM - 21/01/2023 02:40 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.273/S1017/210123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.273/S934/210123 | MSCP site, Southeast fence, walkway | 1.0/100 | <0.01 |
| S110355.273/6530/210123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.273/S894/210123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.273/S561/210123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | Rejected: Pump Moved | |
| S110355.273/S154/210123 | PSB site, northern end, fencing along Redbank Rd | 1.0/100 | <0.01 |
| S110355.273/S1038/210123 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.273/S1012/210123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |
| S110355.273/S511/210123 | PSB site, northern end, temp fencing between clean and dirt zone | 2.0/100 | <0.01 |
| S110355.273/S080/210123 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.273/S197/210123 | Mons Road, before boom gate, fencing | 1.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

23 January 2023

| | | | |
|---|---|---|---|
| S110355.273/S528/210123 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.273/S498/210123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

23 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

23 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

23 January 2023

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.274-AAM1.v1-23/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 23/01/2023
**Sample Analysis Date:** 23/01/2023
**Period of Sampling:** 23/01/2023 06:40 AM - 23/01/2023 01:59 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.274/S898/230123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.274/S231/230123 | MSCP site, Southeast fence, walkway | 0.0/100 | <0.01 |
| S110355.274/S597/230123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.274/S724/230123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.274/S106/230123 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.274/5793/230123 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.274/S192/230123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |
| S110355.274/S797/230123 | PSB site, northern end, temp fencing between clean and dirt zone | 0.0/100 | <0.01 |
| S110355.274/S850/230123 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.274/S087/230123 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.274/S515/230123 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.274/S1021/230123 | Field Blank | 0.0/100 | NA |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

23 January 2023

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

23 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

23 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

Accredited for compliance with ISO/IEC 17025 - Testing

24 January 2023


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.275-AAM1.v1-24/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 24/01/2023
**Sample Analysis Date:** 24/01/2023
**Period of Sampling:** 24/01/2023 06:40 AM - 24/01/2023 01:41 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.275/S911/240123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.275/S971/240123 | MSCP site, Southeast fence, walkway | 0.0/100 | <0.01 |
| S110355.275/S909/240123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.275/S196/240123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.275/S855/240123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.275/S014/240123 | PSB site, northern end, fencing along Redbank Rd | 1.0/100 | <0.01 |
| S110355.275/S104/240123 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.275/S500/240123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |
| S110355.275/5406/240123 | PSB site, northern end, temp fencing between clean and dirt zone | 0.0/100 | <0.01 |
| S110355.275/S518/240123 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.275/S089/240123 | Mons Road, entry point | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

24 January 2023

| | | | |
|---|---|---|---|
| S110355.275/8656/240123 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.275/S418/240123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

24 January 2023






**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

24 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

25 January 2023

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.276-AAM1.v1-25/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 25/01/2023
**Sample Analysis Date:** 25/01/2023
**Period of Sampling:** 25/01/2023 06:40 AM - 25/01/2023 02:10 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.276/S083/250123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 1.0/100 | <0.01 |
| S110355.276/S205/250123 | MSCP site, Southeast fence, walkway | 1.5/100 | <0.01 |
| S110355.276/4123/250123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.276/0392/250123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.276/S807/250123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.276/S199/250123 | PSB site, northern end, fencing along Redbank Rd | 1.0/100 | <0.01 |
| S110355.276/S813/250123 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.276/S987/250123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |
| S110355.276/S778/250123 | PSB site, northern end, temp fencing between clean and dirt zone | 4.5/100 | <0.01 |
| S110355.276/S332/250123 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.276/3215/250123 | Mons Road, before boom gate, fencing | 1.5/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

25 January 2023

| | | | |
|---|---|---|---|
| S110355.276/S588/250123 | Mons Road, entry point | 1.0/100 | <0.01 |
| S110355.276/S097/250123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

25 January 2023






**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

25 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

30 January 2023

***This report supersedes the report issued on 27/01/2023 bearing reference S110335.278-AAM1.v1-27/01/2023.***

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.278-AAM1.v2-27/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 27/01/2023
**Sample Analysis Date:** 27/01/2023
**Period of Sampling:** 27/01/2023 07:01 AM - 27/01/2023 02:13 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.278/S119/270123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.278/S1032/270123 | MSCP site, North temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.278/S252/270123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.278/3249/270123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.278/S620/270123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.278/6016/270123 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.278/S1039/270123 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.278/S770/270123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |
| S110355.278/3193/270123 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

30 January 2023

| | | | |
|---|---|---|---|
| S110355.278/S716/270123 | PSB site, northern end, temp fencing between clean and dirt zone | 0.0/100 | <0.01 |
| S110355.278/S986/270123 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.278/S408/270123 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.278/S732/270123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

30 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

30 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

30 January 2023

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.279-AAM1.v1-28/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 28/01/2023
**Sample Analysis Date:** 30/01/2023
**Period of Sampling:** 28/01/2023 06:40 AM - 28/01/2023 02:40 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.279/8972/280123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.279/S799/280123 | MSCP site, North temp fencing in middle of site, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.279/S962/280123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.279/5489/280123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.279/S946/280123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.279/S337/280123 | PSB site, northern end, fencing along Redbank Rd | 2.0/100 | <0.01 |
| S110355.279/S1036/280123 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.279/3459/280123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |
| S110355.279/S237/280123 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.279/S1040/280123 | PSB site, northern end, temp fencing between clean and dirt zone | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

30 January 2023

| | | | |
|---|---|---|---|
| S110355.279/5421/280123 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.279/S974/280123 | Mons Road, entry point | 1.0/100 | <0.01 |
| S110355.279/6568/280123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

30 January 2023






**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

30 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

30 January 2023

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.280-AAM1.v1-30/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 30/01/2023
**Sample Analysis Date:** 30/01/2023
**Period of Sampling:** 30/01/2023 06:40 AM - 30/01/2023 01:49 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.280/S571/300123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 1.0/100 | <0.01 |
| S110355.280/8983/300123 | MSCP site, North temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.280/S978/300123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.280/5410/300123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.280/S308/300123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.280/S895/300123 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.280/S736/300123 | PSB site, western end, fencing along CASB loading dock | 2.0/100 | <0.01 |
| S110355.280/S240/300123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |
| S110355.280/S1023/300123 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.280/S007/300123 | PSB site, northern end, temp fencing between clean and dirt zone | 2.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

30 January 2023

| | | | |
|---|---|---|---|
| S110355.280/S529/300123 | Mons Road, before boom gate, fencing | 1.0/100 | <0.01 |
| S110355.280/S1024/300123 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.280/S222/300123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

30 January 2023






**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

30 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

31 January 2023

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.281-AAM1.v1-31/01/2023
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 31/01/2023
**Sample Analysis Date:** 31/01/2023
**Period of Sampling:** 31/01/2023 06:40 AM - 31/01/2023 01:45 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.281/S1031/310123 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.281/S941/310123 | MSCP site, North temp fencing in middle of site, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.281/3255/310123 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.281/2117/310123 | MSCP site, northwest, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.281/S016/310123 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.281/S005/310123 | PSB site, northern end, fencing along Redbank Rd | 1.0/100 | <0.01 |
| S110355.281/0604/310123 | PSB site, western end, fencing along CASB loading dock | 1.0/100 | <0.01 |
| S110355.281/S169/310123 | PSB site, eastern corner, temp fencing in site, facing West | 0.0/100 | <0.01 |
| S110355.281/S1018/310123 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.281/S1004/310123 | PSB site, northern end, temp fencing between clean and dirt zone | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

31 January 2023

| | | | |
|---|---|---|---|
| S110355.281/S574/310123 | Mons Road, before boom gate, fencing | 2.0/100 | <0.01 |
| S110355.281/S945/310123 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.281/5839/310123 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: **enquiries@swe.com.au**

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

31 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

31 January 2023




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: enquiries@swe.com.au