SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

01 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** miguel.canas@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.161-AAM1.v1-01/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 01/09/2022
**Sample Analysis Date:** 01/09/2022
**Period of Sampling:** 01/09/2022 06:40 AM - 01/09/2022 01:46 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.161/S603/010922 | MSCP site, southwestern end, adj small courtyard, fencing | 0.0/100 | <0.01 |
| S110355.161/S232/010922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.161/S221/010922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.161/S795/010922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 1.0/100 | <0.01 |
| S110355.161/S724/010922 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.161/S982/010922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.161/S715/010922 | PSB site, eastern end, temp fencing in site | 0.0/100 | <0.01 |
| S110355.161/S501/010922 | PSB site, eastern end, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.161/S548/010922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |
| S110355.161/S224/010922 | Mons Rd, entry point | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

01 September 2022

| | | | |
|---|---|---|---|
| S110355.161/S492/010922 | Mons Rd, before boom gate, fencing | 1.0/100 | <0.01 |
| S110355.161/S090/010922 | Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA
WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

01 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

01 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

02 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing

**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** miguel.canas@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205

**SWE Report Reference:** S110355.162-AAM1.v1-02/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 02/09/2022
**Sample Analysis Date:** 02/09/2022
**Period of Sampling:** 02/09/2022 06:50 AM - 02/09/2022 02:20 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.162/6558/020922 | MSCP site, southwestern end, adj small courtyard, fencing | 0.0/100 | <0.01 |
| S110355.162/8972/020922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.162/S089/020922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.162/3491/020922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.162/S891/020922 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.162/S003/020922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.162/S935/020922 | PSB site, eastern end, temp fencing in site | 2.0/100 | <0.01 |
| S110355.162/3198/020922 | PSB site, eastern end, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.162/S897/020922 | PSB site, eastern end, temp fencing in site | 0.0/100 | <0.01 |
| S110355.162/6255/020922 | Mons Rd, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.162/S979/020922 | Mons Rd, entry point | 0.0/100 | <0.01 |



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

02 September 2022

| | | | |
|---|---|---|---|
| S110355.162/8586/020922 | Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

02 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

02 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

05 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing

**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** miguel.canas@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205

**SWE Report Reference:** S110355.163-AAM1.v1-03/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 03/09/2022
**Sample Analysis Date:** 05/09/2022
**Period of Sampling:** 03/09/2022 06:56 AM - 03/09/2022 03:11 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.163/8983/030922 | MSCP site, southwestern end, adj small courtyard, fencing | 0.0/100 | <0.01 |
| S110355.163/S469/030922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.163/S501/030922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.163/S817/030922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 1.0/100 | <0.01 |
| S110355.163/S240/030922 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.163/S941/030922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.163/S903/030922 | PSB site, eastern end, temp fencing in site | 0.0/100 | <0.01 |
| S110355.163/S974/030922 | PSB site, eastern end, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.163/9267/030922 | PSB site, compound temp fencing between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.163/S515/030922 | Mons Rd, entry point | 1.0/100 | <0.01 |



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

05 September 2022

| | | | |
|---|---|---|---|
| S110355.163/S1074/030922 | Mons Rd, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.163/9092/030922 | Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

05 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

05 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

05 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** miguel.canas@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.164-AAM1.v1-05/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 05/09/2022
**Sample Analysis Date:** 05/09/2022
**Period of Sampling:** 05/09/2022 06:51 AM - 05/09/2022 02:12 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.164/S231/050922 | MSCP site, southwestern end, adj small courtyard, fencing | 0.0/100 | <0.01 |
| S110355.164/S169/050922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.164/S724/050922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.164/8501/050922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.164/S701/050922 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.164/S160/050922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.164/S490/050922 | PSB site, eastern end, temp fencing in site | 0.0/100 | <0.01 |
| S110355.164/S756/050922 | PSB site, eastern end, fencing behind site sheds | 2.0/100 | <0.01 |
| S110355.164/S222/050922 | PSB site, compound temp fencing between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.164/S987/050922 | Mons Rd, entry point | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

05 September 2022

| | | | |
|---|---|---|---|
| S110355.164/S62/050922 | Mons Rd, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.164/S220/050922 | Blank | 0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

05 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

05 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

06 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.165-AAM1.v1-06/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 06/09/2022
**Sample Analysis Date:** 06/09/2022
**Period of Sampling:** 06/09/2022 06:46 AM - 06/09/2022 02:17 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.165/S1020/060922 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.165/S1006/060922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.165/S736/060922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.165/S822/060922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.165/3385/060922 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.165/S890/060922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.165/S492/060922 | PSB site, eastern end, temp fencing in site | 0.0/100 | <0.01 |
| S110355.165/S619/060922 | PSB site, eastern end, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.165/S123/060922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |
| S110355.165/S535/060922 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.165/3399/060922 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

06 September 2022

| | | | |
|---|---|---|---|
| S110355.165/S1017/060922 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

06 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

06 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

07 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** miguel.canas@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.166-AAM1.v1-07/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 07/09/2022
**Sample Analysis Date:** 07/09/2022
**Period of Sampling:** 07/09/2022 06:45 AM - 07/09/2022 02:04 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.166/S909/070922 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.166/S958/070922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.166/6604/070922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.166/S168/070922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.166/S195/070922 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.166/S080/070922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.166/S999/070922 | PSB site, eastern end, temp fencing in site, facing SE | 0.0/100 | <0.01 |
| S110355.166/S481/070922 | PSB site, eastern end, temp fencing in site, facing NE | 0.0/100 | <0.01 |
| S110355.166/S629/070922 | PSB site, eastern end, fencing behind site sheds | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

07 September 2022

| | | | |
|---|---|---|---|
| S110355.166/S487/070922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |
| S110355.166/S899/070922 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.166/S891/070922 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.166/S247/070922 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

07 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

07 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

08 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.167-AAM1.v1-08/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 08/09/2022
**Sample Analysis Date:** 08/09/2022
**Period of Sampling:** 08/09/2022 06:43 AM - 08/09/2022 02:17 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.167/A190/080922 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.167/S252/080922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.167/S335/080922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.167/S747/080922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.167/S802/080922 | PSB site, northern end, fencing along Redbank Rd | 1.0/100 | <0.01 |
| S110355.167/S153/080922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.167/S587/080922 | PSB site, eastern end, temp fencing in site, facing SE | 0.0/100 | <0.01 |
| S110355.167/S845/080922 | PSB site, eastern end, temp fencing in site, facing NE | 0.0/100 | <0.01 |
| S110355.167/S896/080922 | PSB site, eastern end, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.167/S793/080922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

08 September 2022

| | | | |
|---|---|---|---|
| S110355.167/S891/080922 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.167/S907/080922 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.167/S237/080922 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

08 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

08 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

09 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** miguel.canas@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.169-AAM1.v1-09/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 09/09/2022
**Sample Analysis Date:** 09/09/2022
**Period of Sampling:** 09/09/2022 06:47 AM - 09/09/2022 02:13 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.169/S074/090922 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.169/S826/090922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.169/3249/090922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.169/S183/090922 | MSCP site, footpath temp fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.169/S18/090922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 1.0/100 | <0.01 |
| S110355.169/S832/090922 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.169/S058/090922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.169/3436/090922 | PSB site, eastern end, temp fencing in site, facing SE | 0.0/100 | <0.01 |
| S110355.169/3417/090922 | PSB site, eastern end, temp fencing in site, facing NE | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

09 September 2022

| | | | |
|---|---|---|---|
| S110355.169/S107/090922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |
| S110355.169/S813/090922 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.169/S757/090922 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.169/3216/090922 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

09 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

09 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

12 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.170-AAM1.v1-10/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 10/09/2022
**Sample Analysis Date:** 12/09/2022
**Period of Sampling:** 10/09/2022 07:00 AM - 10/09/2022 03:00 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.170/S1013/100922 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.170/S078/100922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.170/3215/100922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.170/S583/100922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 1.0/100 | <0.01 |
| S110355.170/S1010/100922 | PSB site, northern end, fencing along Redbank Rd | 1.0/100 | <0.01 |
| S110355.170/S098/100922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.170/S577/100922 | PSB site, eastern end, temp fencing in site, facing SE | 0.0/100 | <0.01 |
| S110355.170/S232/100922 | PSB site, eastern end, temp fencing in site, facing NE | 1.0/100 | <0.01 |
| S110355.170/3447/100922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |
| S110355.170/3216/100922 | Field Blank | 0.0/100 | NA |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

12 September 2022

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

12 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

12 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.171-AAM1.v1-12/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 12/09/2022
**Sample Analysis Date:** 12/09/2022
**Period of Sampling:** 12/08/2022 07:25 AM - 12/09/2022 02:25 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.171/S754/120922 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.171/S778/120922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.171/3065/120922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.171/S548/120922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.171/S934/120922 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.171/S1007/120922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.171/S1004/120922 | PSB site, eastern end, temp fencing in site, facing SE | 0.0/100 | <0.01 |
| S110355.171/S601/120922 | PSB site, eastern end, temp fencing in site, facing NE | 0.0/100 | <0.01 |
| S110355.171/3459/120922 | PSB site, fencing adjacent entry/crossing | 0.0/100 | <0.01 |
| S110355.171/S1001/120922 | PSB site, northern end, temp fencing between site and compound | 3.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

12 September 2022

| | | | |
|---|---|---|---|
| S110355.171/S808/120922 | Mons Road, entry point | 1.0/100 | <0.01 |
| S110355.171/S231/120922 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.171/S913/120922 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

12 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

12 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

13 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.172-AAM1.v1-13/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 13/09/2022
**Sample Analysis Date:** 13/09/2022
**Period of Sampling:** 13/09/2022 06:50 AM - 13/09/2022 02:26 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.172/S591/130922 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.172/S741/130922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.172/S706/130922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.172/S971/130922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.172/S418/130922 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.172/S461/130922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.172/S338/130922 | PSB site, eastern end, temp fencing in site, facing SE | 0.0/100 | <0.01 |
| S110355.172/S784/130922 | PSB site, eastern end, temp fencing in site, facing NE | 0.0/100 | <0.01 |
| S110355.172/S135/130922 | PSB site, fencing adjacent entry/crossing | 1.0/100 | <0.01 |
| S110355.172/S797/130922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

13 September 2022

| | | | |
|---|---|---|---|
| S110355.172/S558/130922 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.172/S620/130922 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.172/S205/130922 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

13 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

13 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

14 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.173-AAM1.v1-14/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 14/09/2022
**Sample Analysis Date:** 14/09/2022
**Period of Sampling:** 14/09/2022 06:42 AM - 14/09/2022 02:32 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.173/S391/140922 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.173/S526/140922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.173/S986/140922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.173/DP012/140922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.173/S055/140922 | PSB site, northern end, fencing along Redbank Rd | 1.0/100 | <0.01 |
| S110355.173/S791/140922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.173/S154/140922 | PSB site, eastern end, temp fencing in site, facing SE | 0.0/100 | <0.01 |
| S110355.173/S215/140922 | PSB site, eastern end, temp fencing in site, facing NE | 0.0/100 | <0.01 |
| S110355.173/S113/140922 | PSB site, fencing adjacent entry/crossing | 0.0/100 | <0.01 |
| S110355.173/S780/140922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

14 September 2022

| | | | |
|---|---|---|---|
| S110355.173/S740/140922 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.173/S716/140922 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.173/S934/140922 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

14 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

14 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

15 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.174-AAM1.v1-15/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 15/09/2022
**Sample Analysis Date:** 15/09/2022
**Period of Sampling:** 15/09/2022 06:42 AM - 15/09/2022 02:19 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.174/S332/150922 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.174/S083/150922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | Rejected: Damaged filter | |
| S110355.174/6480/150922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.174/S946/150922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.174/S465/150922 | PSB site, northern end, fencing along Redbank Rd | 1.0/100 | <0.01 |
| S110355.174/S097/150922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.174/S227/150922 | PSB site, eastern end, temp fencing in site, facing SE | 1.0/100 | <0.01 |
| S110355.174/S777/150922 | PSB site, eastern end, temp fencing in site, facing NE | 0.0/100 | <0.01 |
| S110355.174/S119/150922 | PSB site, fencing adjacent entry/crossing | 0.0/100 | <0.01 |
| S110355.174/S732/150922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

15 September 2022

| | | | |
|---|---|---|---|
| S110355.174/S997/150922 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.174/S576/150922 | Mons Road, before boom gate, fencing | Rejected: Damaged filter | |
| S110355.174/S108/150922 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

15 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

15 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

16 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.175-AAM1.v1-16/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 16/09/2022
**Sample Analysis Date:** 16/09/2022
**Period of Sampling:** 16/09/2022 06:45 AM - 16/09/2022 01:52 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.175/S154/160922 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 1.0/100 | <0.01 |
| S110355.175/S69/160922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.175/S083/160922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.175/S518/160922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.175/S104/160922 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.175/S229/160922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.175/S852/160922 | PSB site, eastern end, temp fencing in site, facing SE | 0.0/100 | <0.01 |
| S110355.175/9200/160922 | PSB site, eastern end, temp fencing in site, facing NE | 0.0/100 | <0.01 |
| S110355.175/S855/160922 | PSB site, fencing adjacent entry/crossing | 0.0/100 | <0.01 |
| S110355.175/S090/160922 | PSB site, northern end, temp fencing between site and compound | 1.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

16 September 2022

| | | | |
|---|---|---|---|
| S110355.175/S750/160922 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.175/S576/160922 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.175/S528/160922 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

16 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

16 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

19 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.176-AAM1.v1-17/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 17/09/2022
**Sample Analysis Date:** 19/09/2022
**Period of Sampling:** 17/09/2022 07:00 AM - 17/09/2022 03:00 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.176/S979/170922 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.176/S231/170922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.176/S016/170922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.176/S891/170922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.176/S989/170922 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.176/3214/170922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.176/S534/170922 | PSB site, eastern end, temp fencing in site, facing SE | 0.0/100 | <0.01 |
| S110355.176/S974/170922 | PSB site, eastern end, temp fencing in site, facing NE | 0.0/100 | <0.01 |
| S110355.176/S894/170922 | PSB site, fencing adjacent entry/crossing | 0.0/100 | <0.01 |
| S110355.176/8501/170922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

19 September 2022

| | | | |
|---|---|---|---|
| S110355.176/S384/170922 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

19 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

19 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.177-AAM1.v1-19/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 19/09/2022
**Sample Analysis Date:** 19/09/2022
**Period of Sampling:** 19/09/2022 06:50 AM - 19/09/2022 01:50 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.177/3198/190922 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.177/3216/190922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 2.0/100 | <0.01 |
| S110355.177/S220/190922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.177/S104/190922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.177/S058/190922 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.177/S793/190922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.177/S106/190922 | PSB site, eastern end, temp fencing in site, facing SE | 1.0/100 | <0.01 |
| S110355.177/S335/190922 | PSB site, eastern end, temp fencing in site, facing NE | 0.0/100 | <0.01 |
| S110355.177/S490/190922 | PSB site, fencing adjacent entry/crossing | 0.0/100 | <0.01 |
| S110355.177/S587/190922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

19 September 2022

| | | | |
|---|---|---|---|
| S110355.177/S845/190922 | Mons Road, entry point | 3.0/100 | <0.01 |
| S110355.177/S994/190922 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.177/3436/190922 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

19 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

19 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

20 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.178-AAM1.v1-20/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 20/09/2022
**Sample Analysis Date:** 20/09/2022
**Period of Sampling:** 20/09/2022 06:45 AM - 20/09/2022 02:20 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.178/S907/200922 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.178/S009/200922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.178/S1074/200922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.178/5435/200922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 1.0/100 | <0.01 |
| S110355.178/S935/200922 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.178/S393/200922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.178/S469/200922 | PSB site, eastern end, temp fencing in site, facing SE | 0.0/100 | <0.01 |
| S110355.178/S240/200922 | PSB site, eastern end, temp fencing in site, facing NE | 0.0/100 | <0.01 |
| S110355.178/S538/200922 | PSB site, fencing adjacent entry/crossing | 0.0/100 | <0.01 |
| S110355.178/S897/200922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

20 September 2022

| | | | |
|---|---|---|---|
| S110355.178/S891/200922 | Mons Road, entry point | 1.0/100 | <0.01 |
| S110355.178/S511/200922 | Mons Road, before boom gate, fencing | 1.0/100 | <0.01 |
| S110355.178/S089/200922 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

20 September 2022






**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

20 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

21 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.179-AAM1.v1-21/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 21/09/2022
**Sample Analysis Date:** 21/09/2022
**Period of Sampling:** 21/09/2022 06:50 AM - 21/09/2022 02:18 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.179/S059/210922 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 1.0/100 | <0.01 |
| S110355.179/S62/210922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.179/3447/210922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.179/S222/210922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.179/8656/210922 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.179/S003/210922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.179/S747/210922 | PSB site, eastern end, temp fencing in site, facing SE | 1.0/100 | <0.01 |
| S110355.179/S515/210922 | PSB site, eastern end, temp fencing in site, facing NE | 0.0/100 | <0.01 |
| S110355.179/S987/210922 | PSB site, fencing adjacent entry/crossing | 0.0/100 | <0.01 |
| S110355.179/S539/210922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

21 September 2022

| | | | |
|---|---|---|---|
| S110355.179/S851/210922 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.179/S802/210922 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.179/6255/210922 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

21 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

21 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

23 September 2022

NATA WORLD RECOGNISED ACCREDITATION

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** miguel.canas@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.180-AAM1.v1-22/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 22/09/2022
**Sample Analysis Date:** 23/09/2022
**Period of Sampling:** 22/09/2022 06:50 AM - 22/09/2022 02:50 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.180/S098/220922 | MSCP site, southwestern end, adj small courtyard, fencing | 0.0/100 | <0.01 |
| S110355.180/S482/220922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.180/S817/220922 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.180/S501/220922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.180/S232/220922 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.180/S096/220922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.180/S895 /220922 | PSB site, southern end, temp fence in site, facing NE | 0.0/100 | <0.01 |
| S110355.180/S813/220922 | PSB site, southern end, temp fence in site, facing SE | 0.0/100 | <0.01 |
| S110355.180/S969/220922 | PSB site, fencing adjacent entry/crossing | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

23 September 2022

| | | | |
|---|---|---|---|
| S110355.180/S898/220922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |
| S110355.180/S107/220922 | Mons Rd, entry point | 0.0/100 | <0.01 |
| S110355.180/S999/220922 | Mons Rd, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.180/S976/220922 | Field blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

23 September 2022






**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

23 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

23 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** miguel.canas@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.181-AAM1.v1-22/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 22/09/2022
**Sample Analysis Date:** 22/09/2022
**Period of Sampling:** 23/09/2022 06:46 AM - 23/09/2022 02:30 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.181/S466/220922 | MSCP site, southwestern end, adj small courtyard, fencing | 2.0/100 | <0.01 |
| S110355.181/S078/220922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.181/S082/220922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.181/S896/220922 | PSB site, northern end, fencing along Redbank Rd | 1.0/100 | <0.01 |
| S110355.181/S160/220922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.181/0392/220922 | PSB site, southern end, temp fence in site, facing NE | 0.0/100 | <0.01 |
| S110355.181/S548/220922 | PSB site, southern end, temp fence in site, facing SE | 0.0/100 | <0.01 |
| S110355.181/S757/220922 | PSB site, fencing adjacent entry/crossing | 0.0/100 | <0.01 |
| S110355.181/S079/220922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |
| S110355.181/S1010/220922 | Mons Rd, entry point | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

23 September 2022

| | | | |
|---|---|---|---|
| S110355.181/S577/220922 | Mons Rd, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.181/S903/220922 | Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

23 September 2022






**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

23 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

26 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.182-AAM1.v1-24/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 24/09/2022
**Sample Analysis Date:** 26/09/2022
**Period of Sampling:** 24/09/2022 06:50 AM - 24/09/2022 02:50 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 25, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.182/S575/240922 | MSCP site, southwest end, adj. small courtyard, fencing | 0.0/100 | <0.01 |
| S110355.182/S466/240922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.182/8501/240922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.182/S152/240922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.182/3214/240922 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.182/S500/240922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.182/S852/240922 | PSB site, southern end, temp fence in site, facing NE | 0.0/100 | <0.01 |
| S110355.182/S808/240922 | PSB site, southern end, temp fence in site, facing SE | 0.0/100 | <0.01 |
| S110355.182/S227/240922 | PSB site, fencing adjacent entry/crossing | 0.0/100 | <0.01 |
| S110355.182/S391/240922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

26 September 2022

| | | | |
|---|---|---|---|
| S110355.182/S083/240922 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA
WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

26 September 2022






**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

26 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.183-AAM1.v1-26/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 26/09/2022
**Sample Analysis Date:** 26/09/2022
**Period of Sampling:** 26/09/2022 06:45 AM - 26/09/2022 02:21 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.183/S826/260922 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.183/3292/260922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.183/3323/260922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.183/S183/260922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.183/S946/260922 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.183/S588/260922 | PSB site, western end, fencing along CASB loading dock | 1.0/100 | <0.01 |
| S110355.183/S337/260922 | PSB site, eastern end, temp fencing in site, facing SE | 0.0/100 | <0.01 |
| S110355.183/S934/260922 | PSB site, eastern end, temp fencing in site, facing NE | 0.0/100 | <0.01 |
| S110355.183/9092/260922 | PSB site, fencing adjacent entry/crossing | 0.0/100 | <0.01 |
| S110355.183/S1017/260922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

26 September 2022

| | | | |
|---|---|---|---|
| S110355.183/S601/260922 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.183/S18/260922 | Mons Road, before boom gate, fencing | 1.0/100 | <0.01 |
| S110355.183/9267/260922 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

26 September 2022






**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

26 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

Accredited for compliance with ISO/IEC 17025 - Testing

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

27 September 2022


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.184-AAM1.v1-27/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 27/09/2022
**Sample Analysis Date:** 27/09/2022
**Period of Sampling:** 27/09/2022 06:50 AM - 27/09/2022 02:00 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.184/6293/270922 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.184/6480/270922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.184/6262/270922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.184/S69/270922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.184/S832/270922 | PSB site, northern end, fencing along Redbank Rd | 1.0/100 | <0.01 |
| S110355.184/S113/270922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.184/S053/270922 | PSB site, eastern end, temp fencing in site, facing SE | 0.0/100 | <0.01 |
| S110355.184/S1013/270922 | PSB site, eastern end, temp fencing in site, facing NE | 0.0/100 | <0.01 |
| S110355.184/S590/270922 | PSB site, fencing adjacent entry/crossing | 0.0/100 | <0.01 |
| S110355.184/S1004/270922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

27 September 2022

| | | | |
|---|---|---|---|
| S110355.184/6367/270922 | Mons Road, entry point | 1.0/100 | <0.01 |
| S110355.184/6305/270922 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.184/6338/270922 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

27 September 2022






**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

27 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

28 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.185-AAM1.v1-28/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 28/09/2022
**Sample Analysis Date:** 28/09/2022
**Period of Sampling:** 28/09/2022 06:45 AM - 28/09/2022 02:09 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.185/S338/280922 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 0.0/100 | <0.01 |
| S110355.185/S933/280922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.185/S732/280922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.185/S750/280922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.185/S574/280922 | PSB site, northern end, fencing along Redbank Rd | 1.0/100 | <0.01 |
| S110355.185/S135/280922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.185/S526/280922 | PSB site, eastern end, temp fencing in site, facing SE | 0.0/100 | <0.01 |
| S110355.185/S913/280922 | PSB site, eastern end, temp fencing in site, facing NE | 0.0/100 | <0.01 |
| S110355.185/S215/280922 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.185/S101/280922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

28 September 2022

| | | | |
|---|---|---|---|
| S110355.185/3255/280922 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.185/S016/280922 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.185/S052/280922 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

28 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

28 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

29 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.186-AAM1.v1-29/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 29/09/2022
**Sample Analysis Date:** 29/09/2022
**Period of Sampling:** 29/09/2022 06:50 AM - 29/09/2022 02:10 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.186/S1006/290922 | MSCP site, southwestern end, adj small courtyard, between stockpile and public | 1.0/100 | <0.01 |
| S110355.186/S822/290922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 1.0/100 | <0.01 |
| S110355.186/S1020/290922 | MSCP site, adj to Labyrinth Way, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.186/3385/290922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.186/S280/290922 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.186/S102/290922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.186/S535/290922 | PSB site, eastern end, temp fencing in site, facing SE | 0.0/100 | <0.01 |
| S110355.186/S850/290922 | PSB site, eastern end, temp fencing in site, facing NE | 1.0/100 | <0.01 |
| S110355.186/S958/290922 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.186/S247/290922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

29 September 2022

| | | | |
|---|---|---|---|
| S110355.186/S123/290922 | Mons Road, entry point | 0.0/100 | <0.01 |
| S110355.186/S080/290922 | Mons Road, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.186/S992/290922 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

29 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

29 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

30 September 2022

Accredited for compliance with ISO/IEC 17025 - Testing


**Attention:** Danny Khal
**Company:** Ford Civil Contracting Pty Ltd
**Email:** danny.khal@fordcivil.com.au
**Address:** 9 Hattersley Street, Arncliffe NSW 2205


**SWE Report Reference:** S110355.187-AAM1.v1-30/09/2022
**Site Address:** MSCP and PSB, Westmead Hospital
**Sampling Date:** 30/09/2022
**Sample Analysis Date:** 30/09/2022
**Period of Sampling:** 30/09/2022 06:45 AM - 30/09/2022 02:17 PM
**Scope of Work:** Air Monitoring during civil works of asbestos impacted soils
**SWE Laboratory:** Suite 15, 103 Majors Bay Road, Concord NSW 2137

**Accreditation number:** 17092 **Site number:** 18665

**1. Introduction:** Control monitoring for airborne asbestos fibres was undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal/related work.

**2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Volume Measurement, Calibration and Standardisation. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Fibre Count and Mount.

**3. Results:**

| SWE REF. | LOCATION OF SAMPLE | FIBRES/ FIELDS | CONCENTRATION (FIBRES/mL) |
|---|---|---|---|
| S110355.187/S168/300922 | MSCP site, southwestern end, adj small courtyard, fencing | 3.0/100 | <0.01 |
| S110355.187/S619/300922 | MSCP site, temp fencing in middle of site, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.187/S899/300922 | MSCP site, adj to Redbank Rd, temp fencing, between clean and dirty zone | 0.0/100 | <0.01 |
| S110355.187/S701/300922 | MSCP site, northwest end of site, adj old maintenance car park, fencing | 0.0/100 | <0.01 |
| S110355.187/S195/300922 | PSB site, northern end, fencing along Redbank Rd | 0.0/100 | <0.01 |
| S110355.187/3399/300922 | PSB site, western end, fencing along CASB loading dock | 0.0/100 | <0.01 |
| S110355.187/S169/300922 | PSB site, southern end, temp fence in site, facing SE | 0.0/100 | <0.01 |
| S110355.187/S481/300922 | PSB site, eastern end, temp fencing in site, facing NE | 0.0/100 | <0.01 |
| S110355.187/S492/300922 | PSB site, fencing behind site sheds | 0.0/100 | <0.01 |
| S110355.187/S724/300922 | PSB site, northern end, temp fencing between site and compound | 0.0/100 | <0.01 |




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

## CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

30 September 2022

| | | | |
|---|---|---|---|
| S110355.187/S1012/300922 | Mons Rd, entry point | 0.0/100 | <0.01 |
| S110355.187/S487/300922 | Mons Rd, before boom gate, fencing | 0.0/100 | <0.01 |
| S110355.187/S231/300922 | Field Blank | 0.0/100 | NA |

**4. Conclusion:** All air monitoring analytical results reported on in this report are below the lowest detectable level of 0.01 fibres/mL of air.

**Analysed and reported by:**

**Rune Knoph**
Approved Issuer of Reports



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

# APPENDIX A – MONITOR LOCATIONS



**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

30 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au

SAFE WORK & ENVIRONMENTS

NATA WORLD RECOGNISED ACCREDITATION

# CONTROL AIR MONITORING FOR ASBESTOS FIBRES RESULTS

30 September 2022




**Safe Work and Environments Pty Ltd 88127010995**
Suite 15, 103 Majors Bay Road, Concord NSW 2137
Phone: 02 8757 3611
Email: info@swe.com.au