

PARTICULATE MATTER (PM10) DUST MONITORING RESULTS

10 June 2022

Attention: Terry Gauci
Company: AE Smith
Fax/email: terry.gauci@aesmith.com.au
Address: Level 4, Building B, 480 Victoria Road Gladesville, NSW, 2111

WESTMEAD HOSPITAL– MSCP PROJECT – REDBANK ROAD, WESTMEAD, NSW, 2145

SWE Project No.: S110356
Sampling Date: 02/06/2022 – 09/06/2022
Site Address: Westmead Hospital – MSCP Site – Redbank Road, Westmead, NSW 2145
Period of Sampling: 07:00 – 16:00

DATE	SAMPLE ID.	LOCATION OF SAMPLE	Time on	Time off	Result TWA (mg/m ³)
02/06/22	S110356/20220114/020622	Plant Room 933 - External	07:00	16:00	0.003
02/06/22	S110356/20220110/020622	Plant Room 932 - External	07:00	16:00	0.007
02/06/22	S110356/85300111709/020622	Plant Room 942 - Internal	07:00	16:00	0.001
02/06/22	S110356/220220113/020622	Plant Room 941 - External	07:00	16:00	0.001
02/06/22	S110356/20220112/020622	Plant Room 943 - External	07:00	16:00	0.007
02/06/22	S110356/85301122812/020622	Plant Room 931 - External	07:00	16:00	NA*
03/06/22	S110356/20220114/030622	Plant Room 933 - External	07:00	16:00	0.003
03/06/22	S110356/20220110/030622	Plant Room 932 - External	07:00	16:00	0.006
03/06/22	S110356/85300111709/030622	Plant Room 942 - Internal	07:00	16:00	0.001
03/06/22	S110356/220220113/030622	Plant Room 941 - External	07:00	16:00	0.001
03/06/22	S110356/20220112/030622	Plant Room 943 - External	07:00	16:00	0.007
03/06/22	S110356/85301122812/030622	Plant Room 931 - External	07:00	16:00	NA*
04/06/22	S110356/20220114/040622	Plant Room 933 - External	07:00	16:00	0.001
04/06/22	S110356/20220110/040622	Plant Room 932 - External	07:00	16:00	0.003
04/06/22	S110356/85300111709/040622	Plant Room 942 - Internal	07:00	16:00	0.001
04/06/22	S110356/220220113/040622	Plant Room 941 - External	07:00	16:00	0.001

S110356-PM10-DustMonitoring-MSCP-WestmeadHospital-020622-090622

DATE	SAMPLE ID.	LOCATION OF SAMPLE	Time on	Time off	Result TWA (mg/m ³)
04/06/22	S110356/20220112/040622	Plant Room 943 - External	07:00	16:00	0.005
04/06/22	S110356/85301122812/040622	Plant Room 931 - External	07:00	16:00	NA*
05/06/22	S110356/20220114/050622	Plant Room 933 - External	07:00	16:00	0.001
05/06/22	S110356/20220110/050622	Plant Room 932 - External	07:00	16:00	0.003
05/06/22	S110356/85300111709/050622	Plant Room 942 - Internal	07:00	16:00	0.001
05/06/22	S110356/220220113/050622	Plant Room 941 - External	07:00	16:00	0.002
05/06/22	S110356/20220112/050622	Plant Room 943 - External	07:00	16:00	0.003
05/06/22	S110356/85301122812/050622	Plant Room 931 - External	07:00	16:00	NA*
06/06/22	S110356/20220114/060622	Plant Room 933 - External	07:00	16:00	0.001
06/06/22	S110356/20220110/060622	Plant Room 932 - External	07:00	16:00	0.002
06/06/22	S110356/85300111709/060622	Plant Room 942 - Internal	07:00	16:00	0.001
06/06/22	S110356/220220113/060622	Plant Room 941 - External	07:00	16:00	0.001
06/06/22	S110356/20220112/060622	Plant Room 943 - External	07:00	16:00	0.002
06/06/22	S110356/85301122812/060622	Plant Room 931 - External	07:00	16:00	NA*
07/06/22	S110356/20220114/070622	Plant Room 933 - External	07:00	16:00	0.002
07/06/22	S110356/20220110/070622	Plant Room 932 - External	07:00	16:00	0.003
07/06/22	S110356/85300111709/070622	Plant Room 942 - Internal	07:00	16:00	0.001
07/06/22	S110356/220220113/070622	Plant Room 941 - External	07:00	16:00	0.002
07/06/22	S110356/20220112/070622	Plant Room 943 - External	07:00	16:00	0.003
07/06/22	S110356/85301122812/070622	Plant Room 931 - External	07:00	16:00	NA*
08/06/22	S110356/20220114/080622	Plant Room 933 - External	07:00	16:00	0.003
08/06/22	S110356/20220110/080622	Plant Room 932 - External	07:00	16:00	0.005
08/06/22	S110356/85300111709/080622	Plant Room 942 - Internal	07:00	16:00	0.001
08/06/22	S110356/220220113/080622	Plant Room 941 - External	07:00	16:00	0.001
08/06/22	S110356/20220112/080622	Plant Room 943 - External	07:00	16:00	0.004

*=sample void due to monitor failure

Sampling Description: Monitoring for atmospheric particulate matter PM10 dust was undertaken to verify the effectiveness of control measures implemented to prevent dust release as a result of the car park

demolition work.

Sampling Methodology: Dust monitoring was carried out in accordance with National Environment Protection (Ambient Air Quality) Measure (2016) using a 'TSI DustTrak II Aerosol Monitor' to measure dust levels (as mg/m³). The detection limit for the method is 0.001mg/m³.



Conclusion: All dust monitoring results reported on in this report are below the maximum permissible Time Weighted Average (TWA) environmental guideline for PM10 of 0.05mg/m³ as per Table 1 of the National Environment Protection (Ambient Air Quality) Measure (2016).

Should you have any queries regarding this report please do not hesitate to contact the office on (02) 9494 0000 for further information or assistance.

Yours sincerely,

Terry Gauci | Regional Manager (Service) AE Smith, Nuvo & TGS



T1, L1, Trinity Business Campus, 39 Delhi Road, North Ryde, NSW 2113

T +61 2 9494 0000 | M +61 412 660 090

E: terry.gauci@aesmith.com.au

PARTICULATE MATTER (PM10) DUST MONITORING RESULTS

10 June 2022

Attention: Terry Gauci
Company: AE Smith
Fax/email: terry.gauci@aesmith.com.au
Address: Level 4, Building B, 480 Victoria Road Gladesville, NSW, 2111

WESTMEAD HOSPITAL– PSB PROJECT – REDBANK ROAD, WESTMEAD, NSW, 2145

SWE Project No.: S110356
Sampling Date: 02/06/2022 – 09/06/2022
Site Address: Westmead Hospital – PSB Site – Redbank Road, Westmead, NSW 2145
Period of Sampling: 07:00 – 16:00

DATE	SAMPLE ID.	LOCATION OF SAMPLE	Time on	Time off	Result TWA (mg/m ³)
02/06/22	S110356/905/020622	Plant Room 342 - External	07:00	16:00	0.005
02/06/22	S110356/20220113/020622	Plant Room 544 - Internal	07:00	16:00	0.006
02/06/22	S110356/22022011/020622	Ford Civil Site Sheds - External	07:00	16:00	0.001
02/06/22	S110356/220220115/020622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.006
03/06/22	S110356/905/030622	Plant Room 342 - External	07:00	16:00	0.008
03/06/22	S110356/20220113/030622	Plant Room 544 - Internal	07:00	16:00	0.004
03/06/22	S110356/22022011/030622	Ford Civil Site Sheds - External	07:00	16:00	0.001
03/06/22	S110356/220220115/030622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.006
04/06/22	S110356/905/040622	Plant Room 342 - External	07:00	16:00	0.003
04/06/22	S110356/20220113/040622	Plant Room 544 - Internal	07:00	16:00	0.003
04/06/22	S110356/22022011/040622	Ford Civil Site Sheds - External	07:00	16:00	0.001
04/06/22	S110356/220220115/040622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.007
05/06/22	S110356/905/050622	Plant Room 342 - External	07:00	16:00	0.004
05/06/22	S110356/20220113/050622	Plant Room 544 - Internal	07:00	16:00	0.001
05/06/22	S110356/22022011/050622	Ford Civil Site Sheds - External	07:00	16:00	0.001

S110356-PM10-DustMonitoring-PSB-WestmeadHospital-020622-090622

DATE	SAMPLE ID.	LOCATION OF SAMPLE	Time on	Time off	Result TWA (mg/m ³)
05/06/22	S110356/220220115/300522	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.003
06/06/22	S110356/905/060622	Plant Room 342 - External	07:00	16:00	0.002
06/06/22	S110356/20220113/060622	Plant Room 544 - Internal	07:00	16:00	0.002
06/06/22	S110356/22022011/060622	Ford Civil Site Sheds - External	07:00	16:00	0.001
06/06/22	S110356/220220115/060622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.004
07/06/22	S110356/905/070622	Plant Room 342 - External	07:00	16:00	0.003
07/06/22	S110356/20220113/070622	Plant Room 544 - Internal	07:00	16:00	0.002
07/06/22	S110356/2022011/070622	Ford Civil Site Sheds - External	07:00	16:00	0.001
07/06/22	S110356/220220115/070622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.005
08/06/22	S110356/905/080622	Plant Room 342 - External	07:00	16:00	0.004
08/06/22	S110356/20220113/080622	Plant Room 544 - Internal	07:00	16:00	0.002
08/06/22	S110356/2022011/080622	Ford Civil Site Sheds - External	07:00	16:00	0.002
08/06/22	S110356/220220115/080622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.006
09/06/22	S110356/905/090622	Plant Room 342 - External	07:00	16:00	0.004
09/06/22	S110356/20220113/090622	Plant Room 544 - Internal	07:00	16:00	0.003
09/06/22	S110356/2022011/090622	Ford Civil Site Sheds - External	07:00	16:00	0.001
09/06/22	S110356/220220115/090622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.006

*Sample void due to power failure within plant room

Sampling Description: Monitoring for atmospheric particulate matter PM10 dust was undertaken to verify the effectiveness of control measures implemented to prevent dust release as a result of the car park demolition work.



Sampling Methodology: Dust monitoring was carried out in accordance with National Environment Protection (Ambient Air Quality) Measure (2016) using a 'TSI DustTrak II Aerosol Monitor' to measure dust levels (as mg/m³). The detection limit for the method is 0.001mg/m³.

Conclusion: All dust monitoring results reported on in this report are below the maximum permissible Time Weighted Average (TWA) environmental guideline for PM10 of 0.05mg/m³ as per Table 1 of the National Environment Protection (Ambient Air Quality) Measure (2016).

Should you have any queries regarding this report please do not hesitate to contact the office on (02) 9494 0000 for further information or assistance.

Yours sincerely,

Terry Gauci | Regional Manager (Service) AE Smith, Nuvo & TGS



T1, L1, Trinity Business Campus, 39 Delhi Road, North Ryde, NSW 2113
T +61 2 9494 0000 | M +61 412 660 090
E: terry.gauci@aesmith.com.au

PARTICULATE MATTER (PM10) DUST MONITORING RESULTS

17 June 2022

Attention: Terry Gauci
Company: AE Smith
Fax/email: terry.gauci@aesmith.com.au
Address: Level 4, Building B, 480 Victoria Road Gladesville, NSW, 2111

WESTMEAD HOSPITAL– MSCP PROJECT – REDBANK ROAD, WESTMEAD, NSW, 2145

SWE Project No.: S110356
Sampling Date: 10/06/2022 – 16/06/2022
Site Address: Westmead Hospital – MSCP Site – Redbank Road, Westmead, NSW 2145
Period of Sampling: 07:00 – 16:00

DATE	SAMPLE ID.	LOCATION OF SAMPLE	Time on	Time off	Result TWA (mg/m ³)
10/06/22	S110356/20220114/100622	Plant Room 933 - External	07:00	16:00	0.004
10/06/22	S110356/20220110/100622	Plant Room 932 - External	07:00	16:00	0.006
10/06/22	S110356/85300111709/100622	Plant Room 942 - Internal	07:00	16:00	0.001
10/06/22	S110356/220220113/100622	Plant Room 941 - External	07:00	16:00	NA*
10/06/22	S110356/20220112/100622	Plant Room 943 - External	07:00	16:00	0.006
10/06/22	S110356/85301122812/100622	Plant Room 931 - External	07:00	16:00	0.004
11/06/22	S110356/20220114/110622	Plant Room 933 - External	07:00	16:00	0.003
11/06/22	S110356/20220110/110622	Plant Room 932 - External	07:00	16:00	0.006
11/06/22	S110356/85300111709/110622	Plant Room 942 - Internal	07:00	16:00	0.001
11/06/22	S110356/220220113/110622	Plant Room 941 - External	07:00	16:00	NA*
11/06/22	S110356/20220112/110622	Plant Room 943 - External	07:00	16:00	0.007
11/06/22	S110356/85301122812/110622	Plant Room 931 - External	07:00	16:00	0.006
12/06/22	S110356/20220114/120622	Plant Room 933 - External	07:00	16:00	0.002
12/06/22	S110356/20220110/120622	Plant Room 932 - External	07:00	16:00	0.006
12/06/22	S110356/85300111709/120622	Plant Room 942 - Internal	07:00	16:00	0.001
12/06/22	S110356/220220113/120622	Plant Room 941 - External	07:00	16:00	NA*

S110356-PM10-DustMonitoring-MSCP-WestmeadHospital-100622-160622

DATE	SAMPLE ID.	LOCATION OF SAMPLE	Time on	Time off	Result TWA (mg/m ³)
12/06/22	S110356/20220112/120622	Plant Room 943 - External	07:00	16:00	0.006
12/06/22	S110356/85301122812/120622	Plant Room 931 - External	07:00	16:00	0.005
13/06/22	S110356/20220114/130622	Plant Room 933 - External	07:00	16:00	0.003
13/06/22	S110356/20220110/130622	Plant Room 932 - External	07:00	16:00	0.007
13/06/22	S110356/85300111709/130622	Plant Room 942 - Internal	07:00	16:00	0.001
13/06/22	S110356/220220113/130622	Plant Room 941 - External	07:00	16:00	NA*
13/06/22	S110356/20220112/130622	Plant Room 943 - External	07:00	16:00	0.008
13/06/22	S110356/85301122812/130622	Plant Room 931 - External	07:00	16:00	0.007
14/06/22	S110356/20220114/140622	Plant Room 933 - External	07:00	16:00	0.006
14/06/22	S110356/20220110/140622	Plant Room 932 - External	07:00	16:00	0.014
14/06/22	S110356/85300111709/140622	Plant Room 942 - Internal	07:00	16:00	0.002
14/06/22	S110356/220220113/140622	Plant Room 941 - External	07:00	16:00	NA*
14/06/22	S110356/20220112/140622	Plant Room 943 - External	07:00	16:00	0.014
14/06/22	S110356/85301122812/140622	Plant Room 931 - External	07:00	16:00	0.013
15/06/22	S110356/20220114/150622	Plant Room 933 - External	07:00	16:00	0.007
15/06/22	S110356/20220110/150622	Plant Room 932 - External	07:00	16:00	0.014
15/06/22	S110356/85300111709/150622	Plant Room 942 - Internal	07:00	16:00	0.003
15/06/22	S110356/220220113/150622	Plant Room 941 - External	07:00	16:00	NA*
15/06/22	S110356/20220112/150622	Plant Room 943 - External	07:00	16:00	0.014
15/06/22	S110356/85301122812/150622	Plant Room 931 - External	07:00	16:00	0.013
16/06/22	S110356/20220114/160622	Plant Room 933 - External	07:00	16:00	0.003
16/06/22	S110356/20220110/160622	Plant Room 932 - External	07:00	16:00	0.004
16/06/22	S110356/85300111709/160622	Plant Room 942 - Internal	07:00	16:00	0.001
16/06/22	S110356/220220113/160622	Plant Room 941 - External	07:00	16:00	NA*
16/06/22	S110356/20220112/160622	Plant Room 943 - External	07:00	16:00	0.004
16/02/22	S110356/85301122812/160622	Plant Room 931 - External	07:00	16:00	0.004

*=sample void due to monitor failure

Sampling Description: Monitoring for atmospheric particulate matter PM10 dust was undertaken to verify the effectiveness of control measures implemented to prevent dust release as a result of the car park demolition work.

Sampling Methodology: Dust monitoring was carried out in accordance with National Environment Protection (Ambient Air Quality) Measure (2016) using a 'TSI DustTrak II Aerosol Monitor' to measure dust levels (as mg/m³). The detection limit for the method is 0.001mg/m³.

Conclusion: All dust monitoring results reported on in this report are below the maximum permissible Time Weighted Average (TWA) environmental guideline for PM10 of 0.05mg/m³ as per Table 1 of the National Environment Protection (Ambient Air Quality) Measure (2016).

Should you have any queries regarding this report please do not hesitate to contact the office on (02) 9494 0000 for further information or assistance.

Yours sincerely,

Terry Gauci | Regional Manager (Service) AE Smith, Nuvo & TGS



T1, L1, Trinity Business Campus, 39 Delhi Road, North Ryde, NSW 2113
T +61 2 9494 0000 | M +61 412 660 090
E: terry.gauci@aesmith.com.au

PARTICULATE MATTER (PM10) DUST MONITORING RESULTS

17 June 2022

Attention: Terry Gauci
Company: AE Smith
Fax/email: terry.gauci@aesmith.com.au
Address: Level 4, Building B, 480 Victoria Road Gladesville, NSW, 2111

WESTMEAD HOSPITAL- PSB PROJECT – REDBANK ROAD, WESTMEAD, NSW, 2145

SWE Project No.: S110356
Sampling Date: 10/06/2022 – 16/06/2022
Site Address: Westmead Hospital – PSB Site – Redbank Road, Westmead, NSW 2145
Period of Sampling: 07:00 – 16:00

DATE	SAMPLE ID.	LOCATION OF SAMPLE	Time on	Time off	Result TWA (mg/m ³)
10/06/22	S110356/905/100622	Plant Room 342 - External	07:00	16:00	0.008
10/06/22	S110356/20220113/100622	Plant Room 544 - Internal	07:00	16:00	0.003
10/06/22	S110356/22022011/100622	Ford Civil Site Sheds - External	07:00	16:00	0.001
10/06/22	S110356/220220115/100622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.007
11/06/22	S110356/905/110622	Plant Room 342 - External	07:00	16:00	0.006
11/06/22	S110356/20220113/110622	Plant Room 544 - Internal	07:00	16:00	0.004
11/06/22	S110356/22022011/110622	Ford Civil Site Sheds - External	07:00	16:00	0.001
11/06/22	S110356/220220115/110622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.006
12/06/22	S110356/905/120622	Plant Room 342 - External	07:00	16:00	0.002
12/06/22	S110356/20220113/120622	Plant Room 544 - Internal	07:00	16:00	0.004
12/06/22	S110356/22022011/120622	Ford Civil Site Sheds - External	07:00	16:00	0.001
12/06/22	S110356/220220115/120622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.006
13/06/22	S110356/905/130622	Plant Room 342 - External	07:00	16:00	0.01
13/06/22	S110356/20220113/130622	Plant Room 544 - Internal	07:00	16:00	0.005
13/06/22	S110356/22022011/130622	Ford Civil Site Sheds - External	07:00	16:00	0.001

S110356-PM10-DustMonitoring-PSB-WestmeadHospital-100622-160622

DATE	SAMPLE ID.	LOCATION OF SAMPLE	Time on	Time off	Result TWA (mg/m ³)
13/06/22	S110356/220220115/130622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.007
14/06/22	S110356/905/140622	Plant Room 342 - External	07:00	16:00	0.03
14/06/22	S110356/20220113/140622	Plant Room 544 - Internal	07:00	16:00	0.008
14/06/22	S110356/220220111/140622	Ford Civil Site Sheds - External	07:00	16:00	0.002
14/06/22	S110356/220220115/140622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.01
15/06/22	S110356/905/150622	Plant Room 342 - External	07:00	16:00	0.031
15/06/22	S110356/20220113/150622	Plant Room 544 - Internal	07:00	16:00	0.008
15/06/22	S110356/20220111/150622	Ford Civil Site Sheds - External	07:00	16:00	0.002
15/06/22	S110356/220220115/150622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.01
16/06/22	S110356/905/160622	Plant Room 342 - External	07:00	16:00	0.003
16/06/22	S110356/20220113/160622	Plant Room 544 - Internal	07:00	16:00	0.003
16/06/22	S110356/20220111/160622	Ford Civil Site Sheds - External	07:00	16:00	0.001
16/06/22	S110356/220220115/160622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.004

*Sample void due to power failure within plant room

Sampling Description: Monitoring for atmospheric particulate matter PM10 dust was undertaken to verify the effectiveness of control measures implemented to prevent dust release as a result of the car park demolition work.

Sampling Methodology: Dust monitoring was carried out in accordance with National Environment Protection (Ambient Air Quality) Measure (2016) using a 'TSI DustTrak II Aerosol Monitor' to measure dust levels (as mg/m³). The detection limit for the method is 0.001mg/m³.

Conclusion: All dust monitoring results reported on in this report are below the maximum permissible Time Weighted Average (TWA) environmental guideline for PM10 of 0.05mg/m³ as per Table 1 of the National Environment Protection (Ambient Air Quality) Measure (2016).

Should you have any queries regarding this report please do not hesitate to contact the office on (02) 9494 0000 for further information or assistance.

Yours sincerely,

Terry Gauci | Regional Manager (Service) AE Smith, Nuvo & TGS



T1, L1, Trinity Business Campus, 39 Delhi Road, North Ryde, NSW 2113
T +61 2 9494 0000 | M +61 412 660 090
E: terry.gauci@aesmith.com.au

PARTICULATE MATTER (PM10) DUST MONITORING RESULTS

27 June 2022

Attention: Terry Gauci
Company: AE Smith
Fax/email: terry.gauci@aesmith.com.au
Address: Level 4, Building B, 480 Victoria Road Gladesville, NSW, 2111

WESTMEAD HOSPITAL– MSCP PROJECT – REDBANK ROAD, WESTMEAD, NSW, 2145

SWE Project No.: S110356
Sampling Date: 17/06/2022 – 23/06/2022
Site Address: Westmead Hospital – MSCP Site – Redbank Road, Westmead, NSW 2145
Period of Sampling: 07:00 – 16:00

DATE	SAMPLE ID.	LOCATION OF SAMPLE	Time on	Time off	Result TWA (mg/m ³)
17/06/22	S110356/20220114/170622	Plant Room 933 - External	07:00	16:00	0.004
17/06/22	S110356/20220110/170622	Plant Room 932 - External	07:00	16:00	0.009
17/06/22	S110356/85300111709/170622	Plant Room 942 - Internal	07:00	16:00	0.002
17/06/22	S110356/220220113/170622	Plant Room 941 - External	07:00	16:00	NA*
17/06/22	S110356/20220112/170622	Plant Room 943 - External	07:00	16:00	0.008
17/06/22	S110356/85301122812/170622	Plant Room 931 - External	07:00	16:00	0.008
18/06/22	S110356/20220114/180622	Plant Room 933 - External	07:00	16:00	0.003
18/06/22	S110356/20220110/180622	Plant Room 932 - External	07:00	16:00	0.006
18/06/22	S110356/85300111709/180622	Plant Room 942 - Internal	07:00	16:00	0.002
18/06/22	S110356/220220113/180622	Plant Room 941 - External	07:00	16:00	NA*
18/06/22	S110356/20220112/180622	Plant Room 943 - External	07:00	16:00	0.007
18/06/22	S110356/85301122812/180622	Plant Room 931 - External	07:00	16:00	0.005
19/06/22	S110356/20220114/190622	Plant Room 933 - External	07:00	16:00	0.003
19/06/22	S110356/20220110/190622	Plant Room 932 - External	07:00	16:00	0.007
19/06/22	S110356/85300111709/190622	Plant Room 942 - Internal	07:00	16:00	0.001
19/06/22	S110356/220220113/190622	Plant Room 941 - External	07:00	16:00	NA*

S110356-PM10-DustMonitoring-MSCP-WestmeadHospital-170622-230622

DATE	SAMPLE ID.	LOCATION OF SAMPLE	Time on	Time off	Result TWA (mg/m ³)
19/06/22	S110356/20220112/190622	Plant Room 943 - External	07:00	16:00	0.008
19/06/22	S110356/85301122812/190622	Plant Room 931 - External	07:00	16:00	0.007
20/06/22	S110356/20220114/200622	Plant Room 933 - External	07:00	16:00	0.004
20/06/22	S110356/20220110/200622	Plant Room 932 - External	07:00	16:00	0.013
20/06/22	S110356/85300111709/200622	Plant Room 942 - Internal	07:00	16:00	0.002
20/06/22	S110356/220220113/200622	Plant Room 941 - External	07:00	16:00	NA*
20/06/22	S110356/20220112/200622	Plant Room 943 - External	07:00	16:00	0.015
20/06/22	S110356/85301122812/200622	Plant Room 931 - External	07:00	16:00	0.013
21/06/22	S110356/20220114/210622	Plant Room 933 - External	07:00	16:00	0.004
21/06/22	S110356/20220110/210622	Plant Room 932 - External	07:00	16:00	0.009
21/06/22	S110356/85300111709/210622	Plant Room 942 - Internal	07:00	16:00	0.002
21/06/22	S110356/220220113/210622	Plant Room 941 - External	07:00	16:00	NA*
21/06/22	S110356/20220112/210622	Plant Room 943 - External	07:00	16:00	0.01
21/06/22	S110356/85301122812/210622	Plant Room 931 - External	07:00	16:00	0.008
22/06/22	S110356/20220114/220622	Plant Room 933 - External	07:00	16:00	0.003
22/06/22	S110356/20220110/220622	Plant Room 932 - External	07:00	16:00	0.007
22/06/22	S110356/85300111709/220622	Plant Room 942 - Internal	07:00	16:00	0.001
22/06/22	S110356/220220113/220622	Plant Room 941 - External	07:00	16:00	NA*
22/06/22	S110356/20220112/220622	Plant Room 943 - External	07:00	16:00	0.007
22/06/22	S110356/85301122812/220622	Plant Room 931 - External	07:00	16:00	0.006
23/06/22	S110356/20220114/230622	Plant Room 933 - External	07:00	16:00	0.003
23/06/22	S110356/20220110/230622	Plant Room 932 - External	07:00	16:00	0.005
23/06/22	S110356/85300111709/230622	Plant Room 942 - Internal	07:00	16:00	0.001
23/06/22	S110356/220220113/230622	Plant Room 941 - External	07:00	16:00	NA*
23/06/22	S110356/20220112/230622	Plant Room 943 - External	07:00	16:00	0.006
23/02/22	S110356/85301122812/230622	Plant Room 931 - External	07:00	16:00	0.005

*=sample void due to monitor failure

Sampling Description: Monitoring for atmospheric particulate matter PM10 dust was undertaken to verify the effectiveness of control measures implemented to prevent dust release as a result of the car park demolition work.

Sampling Methodology: Dust monitoring was carried out in accordance with National Environment Protection (Ambient Air Quality) Measure (2016) using a 'TSI DustTrak II Aerosol Monitor' to measure dust levels (as mg/m³). The detection limit for the method is 0.001mg/m³.

Conclusion: All dust monitoring results reported on in this report are below the maximum permissible Time Weighted Average (TWA) environmental guideline for PM10 of 0.05mg/m³ as per Table 1 of the National Environment Protection (Ambient Air Quality) Measure (2016).

Should you have any queries regarding this report please do not hesitate to contact the office on (02) 9494 0000 for further information or assistance.

Yours sincerely,

Terry Gauci | Regional Manager (Service) AE Smith, Nuvo & TGS



T1, L1, Trinity Business Campus, 39 Delhi Road, North Ryde, NSW 2113
T +61 2 9494 0000 | M +61 412 660 090
E: terry.gauci@aesmith.com.au

PARTICULATE MATTER (PM10) DUST MONITORING RESULTS

27 June 2022

Attention: Terry Gauci
Company: AE Smith
Fax/email: terry.gauci@aesmith.com.au
Address: Level 4, Building B, 480 Victoria Road Gladesville, NSW, 2111

WESTMEAD HOSPITAL- PSB PROJECT – REDBANK ROAD, WESTMEAD, NSW, 2145

SWE Project No.: S110356
Sampling Date: 17/06/2022 – 23/06/2022
Site Address: Westmead Hospital – PSB Site – Redbank Road, Westmead, NSW 2145
Period of Sampling: 07:00 – 16:00

DATE	SAMPLE ID.	LOCATION OF SAMPLE	Time on	Time off	Result TWA (mg/m ³)
17/06/22	S110356/905/170622	Plant Room 342 - External	07:00	16:00	0.005
17/06/22	S110356/20220113/170622	Plant Room 544 - Internal	07:00	16:00	0.005
17/06/22	S110356/22022011/170622	Ford Civil Site Sheds - External	07:00	16:00	0.001
17/06/22	S110356/220220115/170622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.007
18/06/22	S110356/905/180622	Plant Room 342 - External	07:00	16:00	0.003
18/06/22	S110356/20220113/180622	Plant Room 544 - Internal	07:00	16:00	0.004
18/06/22	S110356/22022011/180622	Ford Civil Site Sheds - External	07:00	16:00	0.001
18/06/22	S110356/220220115/180622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.006
19/06/22	S110356/905/190622	Plant Room 342 - External	07:00	16:00	0.004
19/06/22	S110356/20220113/190622	Plant Room 544 - Internal	07:00	16:00	0.005
19/06/22	S110356/22022011/190622	Ford Civil Site Sheds - External	07:00	16:00	0.001
19/06/22	S110356/220220115/190622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.006
20/06/22	S110356/905/200622	Plant Room 342 - External	07:00	16:00	0.014
20/06/22	S110356/20220113/200622	Plant Room 544 - Internal	07:00	16:00	0.011
20/06/22	S110356/22022011/200622	Ford Civil Site Sheds - External	07:00	16:00	0.002

S110356-PM10-DustMonitoring-PSB-WestmeadHospital-170622-230622

DATE	SAMPLE ID.	LOCATION OF SAMPLE	Time on	Time off	Result TWA (mg/m ³)
20/06/22	S110356/220220115/200622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.007
21/06/22	S110356/905/210622	Plant Room 342 - External	07:00	16:00	0.012
21/06/22	S110356/20220113/210622	Plant Room 544 - Internal	07:00	16:00	0.007
21/06/22	S110356/22022011/210622	Ford Civil Site Sheds - External	07:00	16:00	0.002
21/06/22	S110356/220220115/210622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.007
22/06/22	S110356/905/220622	Plant Room 342 - External	07:00	16:00	0.008
22/06/22	S110356/20220113/220622	Plant Room 544 - Internal	07:00	16:00	0.006
22/06/22	S110356/2022011/220622	Ford Civil Site Sheds - External	07:00	16:00	0.001
22/06/22	S110356/220220115/220622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.007
23/06/22	S110356/905/230622	Plant Room 342 - External	07:00	16:00	0.007
23/06/22	S110356/20220113/230622	Plant Room 544 - Internal	07:00	16:00	0.005
23/06/22	S110356/2022011/230622	Ford Civil Site Sheds - External	07:00	16:00	0.001
23/06/22	S110356/220220115/230622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.007

*Sample void due to power failure within plant room

Sampling Description: Monitoring for atmospheric particulate matter PM10 dust was undertaken to verify the effectiveness of control measures implemented to prevent dust release as a result of the car park demolition work.

Sampling Methodology: Dust monitoring was carried out in accordance with National Environment Protection (Ambient Air Quality) Measure (2016) using a 'TSI DustTrak II Aerosol Monitor' to measure dust levels (as mg/m³). The detection limit for the method is 0.001mg/m³.

Conclusion: All dust monitoring results reported on in this report are below the maximum permissible Time Weighted Average (TWA) environmental guideline for PM10 of 0.05mg/m³ as per Table 1 of the National Environment Protection (Ambient Air Quality) Measure (2016).

Should you have any queries regarding this report please do not hesitate to contact the office on (02) 9494 0000 for further information or assistance.

Yours sincerely,

Terry Gauci | Regional Manager (Service) AE Smith, Nuvo & TGS



T1, L1, Trinity Business Campus, 39 Delhi Road, North Ryde, NSW 2113
T +61 2 9494 0000 | M +61 412 660 090
E: terry.gauci@aesmith.com.au

PARTICULATE MATTER (PM10) DUST MONITORING RESULTS

05 July 2022

Attention: Terry Gauci
Company: AE Smith
Fax/email: terry.gauci@aesmith.com.au
Address: Level 4, Building B, 480 Victoria Road Gladesville, NSW, 2111

WESTMEAD HOSPITAL– MSCP PROJECT – REDBANK ROAD, WESTMEAD, NSW, 2145

SWE Project No.: S110356
Sampling Date: 24/06/2022 – 30/06/2022
Site Address: Westmead Hospital – MSCP Site – Redbank Road, Westmead, NSW 2145
Period of Sampling: 07:00 – 16:00

DATE	SAMPLE ID.	LOCATION OF SAMPLE	Time on	Time off	Result TWA (mg/m ³)
24/06/22	S110356/20220114/240622	Plant Room 933 - External	07:00	16:00	0.002
24/06/22	S110356/20220110/240622	Plant Room 932 - External	07:00	16:00	0.004
24/06/22	S110356/85300111709/240622	Plant Room 942 - Internal	07:00	16:00	0.001
24/06/22	S110356/220220113/240622	Plant Room 941 - External	07:00	16:00	0.001
24/06/22	S110356/20220112/240622	Plant Room 943 - External	07:00	16:00	0.005
24/06/22	S110356/85301122812/240622	Plant Room 931 - External	07:00	16:00	0.004
25/06/22	S110356/20220114/250622	Plant Room 933 - External	07:00	16:00	0.002
25/06/22	S110356/20220110/250622	Plant Room 932 - External	07:00	16:00	0.003
25/06/22	S110356/85300111709/250622	Plant Room 942 - Internal	07:00	16:00	0.001
25/06/22	S110356/220220113/250622	Plant Room 941 - External	07:00	16:00	0.001
25/06/22	S110356/20220112/250622	Plant Room 943 - External	07:00	16:00	0.005
25/06/22	S110356/85301122812/250622	Plant Room 931 - External	07:00	16:00	0.004
26/06/22	S110356/20220114/260622	Plant Room 933 - External	07:00	16:00	0.001
26/06/22	S110356/20220110/260622	Plant Room 932 - External	07:00	16:00	0.004
26/06/22	S110356/85300111709/260622	Plant Room 942 - Internal	07:00	16:00	0.001
26/06/22	S110356/220220113/260622	Plant Room 941 - External	07:00	16:00	0.001

S110356-PM10-DustMonitoring-MSCP-WestmeadHospital-240622-300622

DATE	SAMPLE ID.	LOCATION OF SAMPLE	Time on	Time off	Result TWA (mg/m ³)
26/06/22	S110356/20220112/260622	Plant Room 943 - External	07:00	16:00	0.005
26/06/22	S110356/85301122812/260622	Plant Room 931 - External	07:00	16:00	0.004
27/06/22	S110356/20220114/270622	Plant Room 933 - External	07:00	16:00	0.005
27/06/22	S110356/20220110/270622	Plant Room 932 - External	07:00	16:00	0.009
27/06/22	S110356/85300111709/270622	Plant Room 942 - Internal	07:00	16:00	0.002
27/06/22	S110356/220220113/270622	Plant Room 941 - External	07:00	16:00	0.002
27/06/22	S110356/20220112/270622	Plant Room 943 - External	07:00	16:00	0.009
27/06/22	S110356/85301122812/270622	Plant Room 931 - External	07:00	16:00	0.009
28/06/22	S110356/20220114/280622	Plant Room 933 - External	07:00	16:00	0.003
28/06/22	S110356/20220110/280622	Plant Room 932 - External	07:00	16:00	0.007
28/06/22	S110356/85300111709/280622	Plant Room 942 - Internal	07:00	16:00	0.001
28/06/22	S110356/220220113/280622	Plant Room 941 - External	07:00	16:00	0.001
28/06/22	S110356/20220112/280622	Plant Room 943 - External	07:00	16:00	0.008
28/06/22	S110356/85301122812/280622	Plant Room 931 - External	07:00	16:00	0.007
29/06/22	S110356/20220114/290622	Plant Room 933 - External	07:00	16:00	0.005
29/06/22	S110356/20220110/290622	Plant Room 932 - External	07:00	16:00	0.01
29/06/22	S110356/85300111709/290622	Plant Room 942 - Internal	07:00	16:00	0.001
29/06/22	S110356/220220113/290622	Plant Room 941 - External	07:00	16:00	0.001
29/06/22	S110356/20220112/290622	Plant Room 943 - External	07:00	16:00	0.012
29/06/22	S110356/85301122812/290622	Plant Room 931 - External	07:00	16:00	0.01
30/06/22	S110356/20220114/300622	Plant Room 933 - External	07:00	16:00	0.006
30/06/22	S110356/20220110/300622	Plant Room 932 - External	07:00	16:00	0.01
30/06/22	S110356/85300111709/300622	Plant Room 942 - Internal	07:00	16:00	0.002
30/06/22	S110356/220220113/300622	Plant Room 941 - External	07:00	16:00	0.001
30/06/22	S110356/20220112/300622	Plant Room 943 - External	07:00	16:00	0.01

S110356-PM10-DustMonitoring-MSCP-WestmeadHospital-240622-300622

DATE	SAMPLE ID.	LOCATION OF SAMPLE	Time on	Time off	Result TWA (mg/m ³)
30/06/22	S110356/85301122812/300622	Plant Room 931 - External	07:00	16:00	0.009

*=sample void due to monitor failure

Sampling Description: Monitoring for atmospheric particulate matter PM10 dust was undertaken to verify the effectiveness of control measures implemented to prevent dust release as a result of the car park demolition work.

Sampling Methodology: Dust monitoring was carried out in accordance with National Environment Protection (Ambient Air Quality) Measure (2016) using a 'TSI DustTrak II Aerosol Monitor' to measure dust levels (as mg/m³). The detection limit for the method is 0.001mg/m³.

Conclusion: All dust monitoring results reported on in this report are below the maximum permissible Time Weighted Average (TWA) environmental guideline for PM10 of 0.05mg/m³ as per Table 1 of the National Environment Protection (Ambient Air Quality) Measure (2016).

Should you have any queries regarding this report please do not hesitate to contact the office on (02) 9494 0000 for further information or assistance.

Yours sincerely,

Terry Gauci | Regional Manager (Service) AE Smith, Nuvo & TGS



T1, L1, Trinity Business Campus, 39 Delhi Road, North Ryde, NSW 2113
T +61 2 9494 0000 | M +61 412 660 090
E: terry.gauci@aesmith.com.au

PARTICULATE MATTER (PM10) DUST MONITORING RESULTS

05 July 2022

Attention: Terry Gauci
Company: AE Smith
Fax/email: terry.gauci@aesmith.com.au
Address: Level 4, Building B, 480 Victoria Road Gladesville, NSW, 2111

WESTMEAD HOSPITAL- PSB PROJECT – REDBANK ROAD, WESTMEAD, NSW, 2145

SWE Project No.: S110356
Sampling Date: 24/06/2022 – 30/06/2022
Site Address: Westmead Hospital – PSB Site – Redbank Road, Westmead, NSW 2145
Period of Sampling: 07:00 – 16:00

DATE	SAMPLE ID.	LOCATION OF SAMPLE	Time on	Time off	Result TWA (mg/m ³)
24/06/22	S110356/905/240622	Plant Room 342 - External	07:00	16:00	0.009
24/06/22	S110356/20220113/240622	Plant Room 544 - Internal	07:00	16:00	0.006
24/06/22	S110356/220220115/240622	Ford Civil Site Sheds - External	07:00	16:00	0.001
24/06/22	S110356/20222011/240622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.006
25/06/22	S110356/905/250622	Plant Room 342 - External	07:00	16:00	0.007
25/06/22	S110356/20220113/250622	Plant Room 544 - Internal	07:00	16:00	0.004
25/06/22	S110356/220220115/250622	Ford Civil Site Sheds - External	07:00	16:00	NA*
25/06/22	S110356/20222011/250622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.004
26/06/22	S110356/905/260622	Plant Room 342 - External	07:00	16:00	0.007
26/06/22	S110356/20220113/260622	Plant Room 544 - Internal	07:00	16:00	0.003
26/06/22	S110356/220220115/260622	Ford Civil Site Sheds - External	07:00	16:00	NA*
26/06/22	S110356/20222011/260622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.004
27/06/22	S110356/905/270622	Plant Room 342 - External	07:00	16:00	0.021
27/06/22	S110356/20220113/270622	Plant Room 544 - Internal	07:00	16:00	0.01
27/06/22	S110356/220220115/270622	Ford Civil Site Sheds - External	07:00	16:00	NA*

S110356-PM10-DustMonitoring-PSB-WestmeadHospital-240622-300622

DATE	SAMPLE ID.	LOCATION OF SAMPLE	Time on	Time off	Result TWA (mg/m ³)
27/06/22	S110356/20222011/270622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.009
28/06/22	S110356/905/280622	Plant Room 342 - External	07:00	16:00	0.015
28/06/22	S110356/20220113/280622	Plant Room 544 - Internal	07:00	16:00	0.008
28/06/22	S110356/220220115/280622	Ford Civil Site Sheds - External	07:00	16:00	NA*
28/06/22	S110356/20222011/280622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.007
29/06/22	S110356/905/290622	Plant Room 342 - External	07:00	16:00	0.024
29/06/22	S110356/20220113/290622	Plant Room 544 - Internal	07:00	16:00	0.009
29/06/22	S110356/220220115/290622	Ford Civil Site Sheds - External	07:00	16:00	NA*
29/06/22	S110356/20222011/290622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.008
30/06/22	S110356/905/300622	Plant Room 342 - External	07:00	16:00	0.018
30/06/22	S110356/20220113/300622	Plant Room 544 - Internal	07:00	16:00	0.007
30/06/22	S110356/220220115/300622	Ford Civil Site Sheds - External	07:00	16:00	NA*
30/06/22	S110356/20222011/300622	CASB – Level 4 Plant Room - Internal	07:00	16:00	0.008

*Sample void due to power failure within plant room

Sampling Description: Monitoring for atmospheric particulate matter PM10 dust was undertaken to verify the effectiveness of control measures implemented to prevent dust release as a result of the car park demolition work.

Sampling Methodology: Dust monitoring was carried out in accordance with National Environment Protection (Ambient Air Quality) Measure (2016) using a 'TSI DustTrak II Aerosol Monitor' to measure dust levels (as mg/m³). The detection limit for the method is 0.001mg/m³.

Conclusion: All dust monitoring results reported on in this report are below the maximum permissible Time Weighted Average (TWA) environmental guideline for PM10 of 0.05mg/m³ as per Table 1 of the National Environment Protection (Ambient Air Quality) Measure (2016).

Should you have any queries regarding this report please do not hesitate to contact the office on (02) 9494 0000 for further information or assistance.

Yours sincerely,

Terry Gauci | Regional Manager (Service) AE Smith, Nuvo & TGS



T1, L1, Trinity Business Campus, 39 Delhi Road, North Ryde, NSW 2113
T +61 2 9494 0000 | M +61 412 660 090
E: terry.gauci@aesmith.com.au